


Township N. VII North, Range N. III East of the 2nd Meridian. Surveyed by A. Henric - 1855
James Hedges 1859.

Description of the Soil on the interior Sectional lines.

Between Sections	Quality &c.	Between Sections	Quality &c.	Between Sections	Quality &c.
33.34	Land very hilly	8.9	Hilly & poor	2.33	Hilly & poor
32.33	ditto	5.8	Same	35.36	Unbroken 2 nd rate M. Oak, Hickory, Gum &c.
28.33	ditto	4.5	Same	16.35	Hilly poor land, timber Oak, Hickory &c.
28.30	ditto	27.28	Same M. Oak, Hickory, Gum &c.	25.36	Same
31.32	Hollow, thin Soil	21.28	Part level 2 nd rate. Part hilly & poor. timber Same	22.26	Same
29.32	ditto	21.22	Level 2 nd rate	23.26	Same
29.30	ditto	16.21	Level & poor	24.25	Same
29.20	ditto	15.16	Same	23.24	Same
19.30	ditto	9.16	Same	14.23	Same
30.31	Good farming land, timber Oak, &c.	9.10	Same	13.24	Same
19.20	Land hilly poor M. Oak, Hickory, Dogwood &c.	4.9	Same	13.14	Same
18.19	Same	3.4	Same	11.14	Same
17.18	Broken & poor M. Oak, Gum, Hickory &c.	30.35	Same	12.13	Same
7.8	Very hilly & poor	27.34	Same	2.11	Same
7.8	Same	26.23	Same	1.12	Same
6.7	Same	22.27	Same	1.2	Same
5.6	Same	22.23	Same		
20.29	Same	15.22	Same		
20.21	Hilly poor & thin soil M. Oak, L. Oak, Hickory, Dogwood &c.	14.15	Same		
19.20	Hilly & poor	10.15	Same		
16.17	Same	10.11	Same		
8.17	Same	3.10	Same		



Township N. VIII North, Range N. III East of the 2nd Meridian. Surveyed by A. Henric - 1815
James Hedges 1819.

Description of the Soil on the interior Sectional lines.

Between Sections	Quality &c	Between Sections	Quality &c	Between Sections	Quality &c
33.34	Land very hilly	38.39	Hilly & poor	2.33	Hilly & poor
32.33	ditto	37.38	Same	35.36	Shallow 2 nd rate. W. Oak, Hickory, Gum &c
28.33	ditto	36.37	Same	26.35	Hilly poor land. Timber Oak, Hickory &c
28.30	ditto	27.28	Same. W. Oak, Hickory, Gum &c	25.34	Same
31.32	Hollow, thin soil	26.27	Low 2 nd rate. Poor hilly & poor timber Same	22.26	Same
29.32	ditto	25.26	Low 2 nd rate	23.26	Same
29.30	ditto	24.25	Low 2 nd rate	24.25	Same
27.30	ditto	16.21	Low 2 nd rate	22.24	Same
27.28	ditto	15.16	Same	14.23	Same
30.31	Good farming land. Timber Oak &c	9.16	Same	12.24	Same
19.20	Land hilly poor W. Oak, Hickory, Gum &c	9.10	Same	13.14	Same
18.19	Same	4.9	Same	11.14	Same
17.18	Broken & poor W. Oak, Gum, Hickory &c	3.4	Same	12.13	Same
7.8	Very hilly & poor	27.34	Same	2.11	Same
7.8	Same	26.27	Same	1.12	Same
6.7	Same	22.27	Same	1.2	Same
5.6	Same	22.23	Same		
20.29	Same	15.22	Same		
20.21	Hilly poor & hilly W. Oak, C. Oak, Hickory, Gum &c	14.15	Same		
17.20	Hilly & poor	10.15	Same		
16.17	Same	10.11	Same		
8.17	Same	3.10	Same		



Office of the Monroe County Surveyor
Trohn Enright-Randolph

Health Services Building
119 West 7th Street
Bloomington, IN 47404
Phone: (812) 349-2570

Dear User,

The following images were obtained in 2017 by the Office of the Monroe County Surveyor from the State Imaging and Microfilm Laboratory at the Indiana State Archives. The field notes and plats for Brown County are stored on microfilm Reel 5923 at the Indiana State Archives. Each page provided by the State Imaging and Microfilm Laboratory is approximately 18MB. Our office combined the pages by Township & Range and reduced the resulting pdfs. This process may have caused some degradation in quality. We will provide unreduced images of specific pages if required. Please contact us at 812-349-2570 or at SurveyorsOffice@co.monroe.in.us to request a higher quality image of any specific page.

The pdfs are bookmarked with the original page numbers as assigned by the State Imaging and Microfilm Laboratory.

Be prepared to provide the county name, reel number, and the required page numbers when requesting full sized images.

If you would like a DVD of an entire county, please provide us with one DVD per county along with a self-addressed, stamped envelope.

Trohn Enright-Randolph
Monroe County Surveyor